# SPEC SHEET + MEASUREMENTS



Wink<sup>®</sup> Men's Premiere Flex<sup>™</sup> V-Neck Top. WW5068

### **Product photo**



- 78/20/2 poly/rayon/spandex
- V-neckline
- Shoulder badge loop
- Left chest pocket with pen slot
- Top-loading front pockets with interior right pocket
- · Side vents
- Wink<sup>®</sup> heat transfer logo at left hem
- Modern fit

## **CARE INSTRUCTIONS**

Machine Wash Cold With Like Colors. Gentle Cycle. Use Only Non-Chlorine Bleach When Needed. Tumble Dry Low. Remove Promptly From Dryer. Cool Iron When Needed.

### **Sketches**





back

# SPEC SHEET + MEASUREMENTS



Wink<sup>®</sup> Men's Premiere Flex<sup>™</sup> V-Neck Top. WW5068

#### PRODUCT MEASUREMENTS

	xs	S	M	L	XL	2XL	3XL	4XL	5XL
Body Length at Back	29	29 1/2	30	30 1/2	31	31 1/2	32 1/4	33	33 3/4
Chest	40	43	46	49	53	57	61	65	69
Set in Sleeve Length	9	9 1/4	9 1/2	9 3/4	10	10 1/4	10 1/2	10 3/4	11
Pocket Height	5 1/2	5 1/2	5 1/2	5 1/2	5 3/4	5 3/4	5 3/4	6	6
Pocket Width	5 1/4	5 1/4	5 1/4	5 1/4	5 1/2	5 1/2	5 1/2	5 3/4	5 3/4

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Set in Sleeve Length: Measure from Center Back neck to shoulder point to sleeve hem.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.

#### SIZE CHARTS


	xs	S	М	L	XL	2XL	3XL	4XL	5XL
Chest	34-35	36-38	39-41	42-45	46-49	50-53	54-57	58-60	61-64

# SPEC SHEET + MEASUREMENTS



 $\mathsf{Wink}^{\mathsf{®}}$  Men's Premiere  $\mathsf{Flex}^{^{\mathsf{TM}}}$  V-Neck Top. WW5068

### HOW TO MEASURE



#### **CHEST**

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

## **COLORS**

