

### Red Kap® Short Sleeve Industrial Work Shirt. SP24

### **Product photo**



Sketches



Red Kap puts the toughest materials and advanced stay-clean technology into this shirt so you get the most out of it. This hardworking IL50 style is tested through 50 industrial launderer washes.

- 4.25-ounce, 65/35 poly/cotton with Touchtex<sup>™</sup> technology which provides breathable comfort lasting colors and stain resistance
- Requires minimal ironing thanks to a wrinkle-resistant finish
- Open collar with sewn-in stays
- Separate two-piece yoke
- 6 buttons with metal collar gripper closure at neck
- Two button-through pockets
- · Bartacked pencil stall on left pocket
- · Industrial laundry friendly

#### **CARE INSTRUCTIONS**

Machine wash, tumble dry.



 ${\sf Red}\;{\sf Kap}^{\tiny{\circledR}}\;{\sf Short}\;{\sf Sleeve}\;{\sf Industrial}\;{\sf Work}\;{\sf Shirt}.\;{\sf SP24}$ 

#### PRODUCT MEASUREMENTS

	SR	MR	LR	XLR	2XLR	3XLR	4XLR	5XLR	6XLR
Body Length at Back	31 1/2	31 5/8	31 3/4	31 7/8	32	32 1/8	32 1/4	32 3/8	32 3/8
Chest	21	23	25	27	29	30 1/2	32	33 1/2	35
Sleeve Length from Center Back	17 5/8	18 1/2	19 3/8	20 1/4	21 1/8	22	22 7/8	23 3/4	24 5/8
Pocket Height	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2	5 1/2
Pocket Width	5	5	5	5	5	5	5	5	5

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest: Measured across the chest one inch below armhole when laid flat.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.




Red Kap® Short Sleeve Industrial Work Shirt. SP24

#### SIZE CHARTS

	SR	MR	LR	XLR	2XLR	3XLR	4XLR	5XLR	6XLR
Chest	34 1/2	38 1/2	42 1/2	46 1/2	50 1/2	53 1/2	56 1/2	59 1/2	62 1/2
	- 38	-42	- 46	- 50	- 53	- 56	- 59	- 62	- 65
Neck	13 5/8	14 5/8	15 5/8	16 5/8	17 5/8	18 5/8	19 5/8	20 5/8	21 5/8
	- 14	- 15	- 16	- 17	- 18	- 19	- 20	- 21	- 22
	1/2	1/2	1/2	1/2	1/2	1/2	1/2	1/2	1/2

### HOW TO MEASURE



Neck Measure around the fullest part of the neck at the base.

Chest Width Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. Arm Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.



Red Kap® Short Sleeve Industrial Work Shirt. SP24

### **COLORS**

