

# SPEC SHEET + MEASUREMENTS

PORT AUTHORITY.

## Port Authority® Long Sleeve Performance Staff Shirt. W401

### Product photo



Be ready to perform your very best with these shirts designed with stain release, odor-fighting and moisture-wicking technologies.

- 3.3-ounce, 100% polyester
- Stain release
- Odor-fighting
- Moisture-wicking
- Wrinkle-resistant
- Open collar
- French placket
- Dyed-to-match buttons
- Left chest pocket
- Rounded adjustable cuffs
- Rental-friendly

### CARE INSTRUCTIONS

Machine wash cold with like colors, do not bleach, tumble dry low, do not use fabric softener, remove promptly, cool iron if needed.

### Sketches



front



back

# SPEC SHEET + MEASUREMENTS

PORT AUTHORITY

## Port Authority® Long Sleeve Performance Staff Shirt. W401

### PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Body Length at Back	28	29	30	31	32	33	33 1/2	34
Chest	20	21 1/2	23	24 1/2	26	27 1/2	29 1/2	31 1/2
Neck Circumference	17	17	17 1/2	18	19	19 3/4	20 1/2	21 1/4
Sleeve Length from Center Back	34	34 3/4	35 1/2	36 1/4	37	37 3/4	38 1/2	39 1/4
Pocket Height	5	5	5 1/4	5 1/4	5 1/4	5 1/4	5 1/4	5 1/2
Pocket Width	4 3/8	4 3/8	4 5/8	4 5/8	4 5/8	4 5/8	4 5/8	4 7/8

**Body Length at Back:** Measured from high point shoulder to finished hem at back.

**Chest:** Measured across the chest one inch below armhole when laid flat.

**Neck Circumference:** Measure from center of button to end of buttonhole along the center of the collar stand.

**Sleeve Length from Center Back:** Measure from Center Back neck to shoulder point to sleeve hem.

**Pocket Height:** Measure from top to bottom at center.

**Pocket Width:** Measure from side to side at top edge.

# SPEC SHEET + MEASUREMENTS


PORT AUTHORITY

Port Authority® Long Sleeve Performance Staff Shirt.  
W401

## SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57
Neck	14 1/2 - 15	15 - 15 1/2	15 1/2 - 16	16 - 16 1/2	16 1/2 - 17	17 - 17 1/2	17 1/2 - 18	18 - 18 1/2
Arm	30 1/2	32	34	35	36 1/2	37 1/2	38 1/2	39 1/2

## HOW TO MEASURE



**Neck** Measure around the fullest part of the neck at the base.  
**Chest Width** Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. **Arm** Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

## COLORS



Black  
PMS BLACK  
C



Graphite  
PMS 7540C



True Blue  
PMS 654C



True Navy  
PMS 533C