SPEC SHEET + MEASUREMENTS

COMFORT COLORS®

Comfort Colors® Lightweight Hooded Sweatshirt. 1467

Product photo



- 6.4-ounce, 100% ring spun US cotton
- · Garment-dyed for a lived-in feel
- · Jersey-lined hood
- · Natural-colored flat drawcord (White flat drawcord on White)
- 1x1 rib knit cuffs and waistband
- · Signature twill label and back neck tape
- · Rolled forward shoulder
- Relaxed fit, seamless body

The garment-dying process infuses each garment with unique character. Please allow for slight color variation in production and washing. Special consideration must also be taken when printing white ink on garment-dyed cotton.

CARE INSTRUCTIONS

Maximum Washing Temperature 30 C, Inside Out, With Like Colors. Only Oxygen/Nonchlorine Bleach Allowed. Tumble Dry At Low Temperature, Max 60 C. Do Not Iron. Do Not Dryclean.

Sketches



front



back

SPEC SHEET + MEASUREMENTS

COMFORT COLORS®

Comfort Colors[®] Lightweight Hooded Sweatshirt. 1467

PRODUCT MEASUREMENTS

	s	М	L	XL	2XL	3XL
Body Length at Back	27	28	29	30	31	32
Chest Width	20	22	24	26	28	30
Sleeve Length from Center Back	33 1/2	34 1/2	35 1/2	36 1/2	37 1/2	38 1/2

Body Length at Back: Measured from high point shoulder to finished hem at back.

Chest Width: Measured across the chest one inch below armhole when laid flat.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

SIZE CHARTS


	S	М	L	XL	2XL	3XL
Chest	37-45 1/2	41-47 1/2	45-50 1/2	49-53	53-56	56

SPEC SHEET + MEASUREMENTS

COMFORT COLORS°

Comfort Colors® Lightweight Hooded Sweatshirt. 1467

HOW TO MEASURE



CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

COLORS







Butter PMS 7401C



Grey PMS 2333C



Hydrangea PMS 651C



PMS 2309C





PMS 0631C



PMS 7514C

Black

PMS 426C



Blue Jean

PMS 2138C

Pepper PMS 2336C White