SPEC SHEET + MEASUREMENTS



Wink[®] Women's Premiere Flex[™] Full-Zip Scrub Jacket. WW4088

Product photo



- 78/20/2 poly/rayon/spandex
- Zippered front closure
- Shoulder badge loop
- · Rib knit cuffs
- · Top-loading front pockets with interior pocket
- · Side vents
- Wink[®] heat transfer logo at left pocket
- Modern fit

CARE INSTRUCTIONS

Machine Wash Cold With Like Colors. Gentle Cycle. Use Only Non-Chlorine Bleach When Needed. Tumble Dry Low. Remove Promptly From Dryer. Cool Iron When Needed.

Sketches





front

back

SPEC SHEET + MEASUREMENTS



Wink[®] Women's Premiere Flex[™] Full-Zip Scrub Jacket. WW4088

PRODUCT MEASUREMENTS

	2XS	xs	S	М	L	XL	2XL	3XL	4XL	5XL
Size	0	2	4-6	8-10	12-14	16-18	20-22	24-26	28-30	32-34
Body Length at Back	26 1/2	27	27 1/2	28 1/4	29	29 3/4	30 1/2	31 1/4	32	32 3/4
Bust	34	37	40	43	46	50	54	58	62	66
Set in Sleeve Length	24	24 1/4	24 1/2	24 5/8	24 3/4	24 7/8	25	25 1/8	25 1/4	25 3/8

Body Length at Back: Measured from high point shoulder to finished hem at back.

Bust: Measured across the chest one inch below armhole when laid flat.

Set in Sleeve Length: Measure from Center Back neck to shoulder point to sleeve hem.

SIZE CHARTS


	2XS	xs	S	М	L	XL	2XL	3XL	4XL	5XL
Size	0	2-4	6-8	10-12	14-16	18-20	22-24	26-28	30-32	34-36
Bust	30-31	32-33	34-35	36-38	39-42	43-46	47-50	51-54	55-58	59-62

SPEC SHEET + MEASUREMENTS



Wink[®] Women's Premiere Flex[™] Full-Zip Scrub Jacket. WW4088

HOW TO MEASURE



BUST

Measure under the arm and around the fullest part of the bust with arms down, keeping tape horizontal.

COLORS



Black PMS PROCESS BLACK C



Ceil Blue PMS 659C



Navy PMS 654C



Pewter PMS 432C



Royal PMS 2145C



Teal Blue PMS 320C





