

Green line denotes Inside Margin
Pink line denotes Outside Bleed Margin
Gray line denotes Die Cut

FRACTIONS & DECIMALS		
$\frac{1}{64}$.0156	$\frac{9}{16}$.5625
$\frac{1}{32}$.0313	$\frac{19}{32}$.5937
$\frac{1}{16}$.0625	$\frac{5}{8}$.625
$\frac{1}{8}$.125	$\frac{21}{32}$.6562
$\frac{3}{16}$.1875	$\frac{11}{16}$.6875
$\frac{1}{4}$.25	$\frac{23}{32}$.7187
$\frac{5}{16}$.3125	$\frac{3}{4}$.750
$\frac{3}{8}$.375	$\frac{25}{32}$.7812
$\frac{7}{16}$.4375	$\frac{13}{16}$.8125
$\frac{1}{2}$.50	$\frac{7}{8}$.875
$\frac{17}{32}$.5312	$\frac{15}{16}$.9375