## **SPEC SHEET + MEASUREMENTS**



### OGIO® Fulcrum 1/4-Zip. OE701

#### **Product photo**



#### **Sketches**







back

### LAYERABLE WARMTH STRETCH FLATLOCK SEAMS FOR COMFORT REFLECTIVE DETAILS

- 7.4-ounce, 95/5 poly/spandex jersey
- · Reflective OGIO heat transfer label for tag-free comfort
- Zip-through cadet collar
- Reflective O heat transfer at back neck
- Reflective welding around zippered chest pocket
- Tonal embossed O pattern at side panels and elbows
- · Set-in sleeves with shaped cuffs
- · Reflective O heat transfer at left cuff
- Slight drop tail hem with reflective O heat transfer at back left hem

#### **CARE INSTRUCTIONS**

Machine Wash Cold. Wash With Similar Colors. Only Non-Chlorine Bleach When Needed. Tumble Dry Medium. Cool Iron if Necessary.

# SPEC SHEET + MEASUREMENTS



OGIO® Fulcrum 1/4-Zip. OE701

#### PRODUCT MEASUREMENTS

	xs	s	М	L	XL	2XL	3XL	4XL
Chest Width	18 1/4	19 3/4	21 1/4	22 3/4	24 1/4	25 3/4	27 3/4	29 3/4
Body Length at Front	26 1/4	27 1/4	28 3/8	29 1/2	30 5/8	31 3/4	32 3/8	33
Sleeve Length	35 1/4	36	36 3/4	37 1/2	38 1/4	39	39 3/4	40 1/2

Chest Width: Measured across the chest one inch below armhole when laid flat.

**Body Length at Front:** Measure from high point shoulder to lowest point of hem at front.

Sleeve Length: Start at center of neck and measure down shoulder, down sleeve to hem.

#### SIZE CHARTS


	xs	s	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57

# SPEC SHEET + MEASUREMENTS



OGIO<sup>®</sup> Fulcrum 1/4-Zip. OE701

#### HOW TO MEASURE



#### **CHEST**

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

#### **COLORS**







Blacktop PMS BLACK C

Electric Blue PMS 2145C

Gear Grey PMS 425C