# **SPEC SHEET + MEASUREMENTS**

#### PORT AUTHORITY.

## Port Authority<sup>®</sup> Short Sleeve SuperPro<sup>™</sup> Twill Shirt. S664

## **Product photo**



A heavy hitter in performance, our SuperPro Twill Shirt easily resists wrinkles while releasing stains. Designed for comfort, this versatile shirt functions well in almost any work environment from the office to food service.

- 3.4-ounce, 55/45 cotton/poly
- Button-down collar
- · Back shoulder pleats
- Dyed-to-match buttons
- · Left chest pocket

#### **CARE INSTRUCTIONS**

Machine wash warm with like colors. Non-chlorine bleach if needed. Tumble dry low. Remove promptly and hang. Warm iron if needed.

## **Sketches**





# SPEC SHEET + MEASUREMENTS

PORT AUTHORITY.

Port Authority<sup>®</sup> Short Sleeve SuperPro<sup>™</sup> Twill Shirt. S664

#### PRODUCT MEASUREMENTS

	xs	S	M	L	XL	2XL	3XL	4XL
Chest	20	21 1/2	23	24 1/2	26	27 1/2	29 1/2	31 1/2
Body Length at Back	29	30	31	32	33	34	34 1/2	35
Sleeve Length from Center Back	17 1/4	18	18 3/4	19 1/2	20 1/4	21	21 3/4	22 1/2
Pocket Height	5 3/8	5 3/8	5 5/8	5 5/8	5 5/8	5 5/8	5 5/8	5 7/8
Pocket Width	4 5/8	4 5/8	5 1/8	5 1/8	5 1/8	5 1/8	5 1/8	5 5/8
Neck	17	17	17 1/2	18	19	19 3/4	20 1/2	21 1/4

Chest: Measured across the chest one inch below armhole when laid flat.

**Body Length at Back:** Measured from high point shoulder to finished hem at back.

Sleeve Length from Center Back: Measure from Center Back neck to shoulder point to sleeve hem.

Pocket Height: Measure from top to bottom at center.

Pocket Width: Measure from side to side at top edge.

**Neck:** Measured from center of button to center of buttonhole.

# **SPEC SHEET + MEASUREMENTS**


#### PORT AUTHORITY.

Port Authority<sup>®</sup> Short Sleeve SuperPro<sup>™</sup> Twill Shirt. S664

#### SIZE CHARTS

	xs	S	М	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57
Neck	16 1/2	16 1/2	17	17 1/2	18 1/2	19 1/4	20	20 3/4

#### HOW TO MEASURE



Neck Measure around the fullest part of the neck at the base.

Chest Width Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal. Arm Place hand on hip. Start at the center of the back of the neck and measure across the shoulder, to the elbow, and then down to the wrist.

## **COLORS**







Monument Grey PMS COOL GRAY 9C



Sterling Grey PMS 425 C



True Blue PMS 654C



True Navy PMS 533C



Ultramarine Blue PMS 7455C



White