

SPEC SHEET + MEASUREMENTS



OGIO® Fulcrum 1/4-Zip. OE701

Product photo



LAYERABLE WARMTH

STRETCH

FLATLOCK SEAMS FOR COMFORT

REFLECTIVE DETAILS

- 7.4-ounce, 95/5 poly/spandex jersey
- Reflective OGIO heat transfer label for tag-free comfort
- Zip-through cadet collar
- Reflective O heat transfer at back neck
- Reflective welding around zippered chest pocket
- Tonal embossed O pattern at side panels and elbows
- Set-in sleeves with shaped cuffs
- Reflective O heat transfer at left cuff
- Slight drop tail hem with reflective O heat transfer at back left hem

CARE INSTRUCTIONS

Machine Wash Cold. Wash With Similar Colors. Only Non-Chlorine Bleach When Needed. Tumble Dry Medium. Cool Iron if Necessary.

Sketches



front



back

SPEC SHEET + MEASUREMENTS



OGIO® Fulcrum 1/4-Zip. OE701

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	18 1/4	19 3/4	21 1/4	22 3/4	24 1/4	25 3/4	27 3/4	29 3/4
Body Length at Front	26 1/4	27 1/4	28 3/8	29 1/2	30 5/8	31 3/4	32 3/8	33
Sleeve Length	35 1/4	36	36 3/4	37 1/2	38 1/4	39	39 3/4	40 1/2

Chest: Measured across the chest one inch below armhole when laid flat.


Body Length at Front: Measure from high point shoulder to lowest point of hem at front.

Sleeve Length: Start at center of neck and measure down shoulder, down sleeve to hem.

SIZE CHARTS

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57

HOW TO MEASURE



CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

SPEC SHEET + MEASUREMENTS



OGIO® Fulcrum 1/4-Zip. OE701

COLORS



Blacktop
PMS BLACK
C



Electric Blue
PMS 2145C



Gear Grey
PMS 425C