

## SPEC SHEET + MEASUREMENTS

COMFORT COLORS®

Comfort Colors® Lightweight Hooded Sweatshirt. 1467

### Product photo



- 6.4-ounce, 100% ring spun US cotton
- Garment-dyed for a lived-in feel
- Jersey-lined hood
- Natural-colored flat drawcord (White flat drawcord on White)
- 1x1 rib knit cuffs and waistband
- Signature twill label and back neck tape
- Rolled forward shoulder
- Relaxed fit, seamless body

The garment-dying process infuses each garment with unique character. Please allow for slight color variation in production and washing. Special consideration must also be taken when printing white ink on garment-dyed cotton.

### CARE INSTRUCTIONS

Maximum Washing Temperature 30 C, Inside Out, With Like Colors. Only Oxygen/Nonchlorine Bleach Allowed. Tumble Dry At Low Temperature, Max 60 C. Do Not Iron. Do Not Dryclean.

### Sketches



front



back

# SPEC SHEET + MEASUREMENTS

COMFORT COLORS®

Comfort Colors® Lightweight Hooded Sweatshirt. 1467

## PRODUCT MEASUREMENTS

|                                | S      | M      | L      | XL     | 2XL    | 3XL    |
|--------------------------------|--------|--------|--------|--------|--------|--------|
| Body Length at Back            | 27     | 28     | 29     | 30     | 31     | 32     |
| Chest                          | 20     | 22     | 24     | 26     | 28     | 30     |
| Sleeve Length from Center Back | 33 1/2 | 34 1/2 | 35 1/2 | 36 1/2 | 37 1/2 | 38 1/2 |

**Body Length at Back:** Measured from high point shoulder to finished hem at back.

**Chest:** Measured across the chest one inch below armhole when laid flat.

**Sleeve Length from Center Back:** Measure from Center Back neck to shoulder point to sleeve hem.

## SIZE CHARTS


|       | S         | M         | L         | XL    | 2XL   | 3XL |
|-------|-----------|-----------|-----------|-------|-------|-----|
| Chest | 37-45 1/2 | 41-47 1/2 | 45-50 1/2 | 49-53 | 53-56 | 56  |

# SPEC SHEET + MEASUREMENTS

COMFORT COLORS®

Comfort Colors® Lightweight Hooded Sweatshirt. 1467

## HOW TO MEASURE



### CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

## COLORS



Black  
PMS 426C



Blue Jean  
PMS 2138C



Butter  
PMS 7401C



Grey  
PMS 2333C



Hydrangea  
PMS 651C



Ivory  
PMS 2309C



Neon Violet  
PMS 0631C



Peachy  
PMS 7514C



Pepper  
PMS 2336C



White