

# SPEC SHEET + MEASUREMENTS



## CornerStone® ANSI 107 Class 3 Heavy-Duty Fleece Full-Zip Hoodie. CSF300

### Product photo



Designed for visibility, this durable heavyweight hoodie is also warm and comfortable.

- 8.6-ounce, 100% polyester smooth-faced fleece
- Black bottom front and cuffs for a cleaner appearance
- Durable, reflective 2-inch tape meets ANSI 107 requirements and provides 360-degree visibility on body and sleeves
- Three-panel hood with drawcord closure
- Taped neck
- Front pouch pockets
- Molded center front zippered closure
- Rib knit cuffs and hem
- This garment must be fully zipped to be in compliance with ANSI 107 standards

### CARE INSTRUCTIONS

Machine Wash Cold. Do Not Use Softener. Only Non-Chlorine Bleach When Needed. Tumble Dry Low. Cool Iron If Necessary.

### Sketches



front



back

# SPEC SHEET + MEASUREMENTS



CornerStone® ANSI 107 Class 3 Heavy-Duty Fleece Full-Zip Hoodie. CSF300

## PRODUCT MEASUREMENTS

|                                | M      | L      | XL     | 2XL | 3XL    | 4XL    | 5XL    |
|--------------------------------|--------|--------|--------|-----|--------|--------|--------|
| Body Length at Back            | 29 1/2 | 30     | 31     | 32  | 32 1/2 | 33     | 33 1/2 |
| Chest                          | 23 1/2 | 25     | 26 1/2 | 28  | 30     | 32     | 34     |
| Sleeve Length from Center Back | 35 3/4 | 36 1/2 | 37 1/4 | 38  | 38 3/4 | 39 1/2 | 40 1/4 |

**Body Length at Back:** Measured from high point shoulder to finished hem at back.

**Chest:** Measured across the chest one inch below armhole when laid flat.

**Sleeve Length from Center Back:** Measure from Center Back neck to shoulder point to sleeve hem.

## SIZE CHARTS

|       | M     | L     | XL    | 2XL   | 3XL   | 4XL   | 5XL   |
|-------|-------|-------|-------|-------|-------|-------|-------|
| Chest | 38-40 | 41-43 | 44-46 | 47-49 | 50-53 | 54-57 | 58-60 |


# SPEC SHEET + MEASUREMENTS



CornerStone® ANSI 107 Class 3 Heavy-Duty Fleece Full-Zip Hoodie. CSF300

## HOW TO MEASURE

---



### CHEST

Measure under the arm and around the fullest part of the chest with arms down, keeping tape horizontal.

## COLORS

---



Safety Orange   Safety Yellow